











May 16, 2002

Presenter

May 16, 2002

Page 1

STS-111/UF2

Flight Readiness Review













Presenter	M. D. Erminge	er	
Date	May 16, 2002	Page	2

Approach and General Description

S&MA held reviews in preparation for the STS-111/UF2 Flight Readiness Review on 3 May, and 14 May, 2002 and is ready to proceed toward launch countdown.

FRR Briefing Overview

- Significant assessments discuss
- Special topics
 - NASA Safety Reporting System (NSRS) discuss
 - Space Shuttle Hazard Analysis discuss
 - Space Shuttle FMEA/CIL discuss
- Space Shuttle and Space Station Independent Assessments none
- Significant Open work discuss
- CoFR Exceptions none
- Open Action Items none













Presenter	M. D. Erminger		
Date	May 16, 2002	Page	3

Significant Assessments

Space Station

Oxygen Elektron Repair Plan and Oxygen Generation

Orbiter

- STS-110 RCS Jet Problems
- Power Static Inverter (PSI) Capacitor Issue

Launch & Landing

STS-110 Front End Processor Failure at T-5 Minutes

SRB

• Power Bus Isolation Supply (PBIS) Capacitor Failure

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presenter	M. D. Erminger			
Date	May 16, 2002	Page	4	

Significant Assessments

RSRM

• STS-107 Right Hand Field Joint Pin Extrusion

<u>SSME</u>

• Engine 2056 Nozzle Contamination – significant open work

ADDITIONAL ASSESSED ITEMS ARE IN THE BACKUP CHARTS













Presenter	M. D. Erminger		
Date	May 16, 2002	Page	5

NSRS Summary

There are no NASA Safety Reporting System reports open that are applicable to STS-111/UF2.

Hazard Analysis Summary

There are no new Accepted Risk hazards identified for STS-111/UF2.

FMEA/CIL Summary

There are no new Criticality 1 failure modes identified for STS-111/UF2.













Presenter	M. D. Erminger			
Date	May 16, 2002	Page	6	

STS-111/UF2 Readiness Statement

With the satisfactory completion of identified open work, Safety and Mission Assurance has no constraints to STS-111/UF2. S&MA has no issues that constrain any of the mission success criteria.

/S/ John Casper	/S/ Shannon Bartell
SR&QA Director, JSC	Director, KSC Safety, Health and Independent Assessment
/S/ Amanda Goodson	/S/ Bill Higgins
S&MA Director, MSFC	Chief, Shuttle S&MA, KSC
/S/ Jerry Holsomback	/S/ Hank Davis
ISS S&MA Manager	HEDS IA Director
/S/ Mark Erminger	/S/ Mike Smiles
SS SR&QA Manager	S&MA Manager, SSC













May 16, 2002 Page 7

STS-111/UF2

Flight Readiness Review

Backup Package













Presenter	M. D. Erminge	er	
Date	May 16, 2002	Page	8

Additional Assessments

Orbiter/GFE

- First Flight/Critical Process Change
 - Midbody Crossover Bracket Re-Design
 - N2 Transfer Hose Quick Disconnect Release Ring
 - Sky Genie Installation Fastener Change
- RMS Direct Drive Switch Cycles
- DSC Transistor Failure Investigation
- Connector Saver Status
- ET Door Drive Actuator Torque Limiter Problem
- T-Handle Age Life test failure
- METOX Update

<u>SRB</u>

- Hydraulic Pump Keenserts
- IEA ATP Power Supply Capacitor Failure
- Nozzle Platform Contact

Launch & Landing

STS-110 MLP LH2 Weld Failure Follow-On Work













Presenter	M. D. Erminger		
Date	May 16, 2002	Page	9

Additional Assessments

KSC Safety Health & Independent Assessment

- MLP GH2 vent-line weld failure with regards to STS-111
- STS-110 incident regarding the MPS cover left in the aft during STS-110 aft closeouts
- MPLM contamination response
- Launch on Need processing of the SSRMS wrist joint
- Payload Late Access Kit mishap during STS-108